

# 2008 – UP FORD TORQUESHIFT(5R110)

## *Delayed reverse, No Reverse, Low Engine Power*

Model years **2008 – up** have included a  
“Transmission Protection Strategy”

This may cause intermittent reverse engagement issues. Performing repetitive shifts from drive to reverse, such as snow plowing can also initiate the vehicles “Engine Speed limiter Strategy”. This may also result in reverse issues. You may experience a 10-20 second delay into reverse, no reverse, or low power from the engine. Strategy will reset after cool down and key cycle.

